

Inspection Photos

Location Name: WELL RANCH-USXAA-66N63W /35NENW

Location #: 306658



Photo #1

Wells Ranch-USXAA 35-19 (05-123-25078) Wellsite
Temporarily Abandoned | TA



Photo #2

Wells Ranch-USX BB AA 35-19,35-03,35-04,35-5,35-06
Battery site

Abandoned: All Equipment Removed
Reclamation progressing
*Formerly served Wells Ranch USX AA 35-14
(Plugged & Abandoned | PA) (prior insp.)*

Inspection Photos

Location Name: WELL RANCH-USXAA-66N63W /35NENW

Location #: 306658



Colorado Oil & Gas Conservation Commission
40.44702, -104.40841, 1438.0m, 150°
02/01/2020 10:24:21 AM

Photo #3

Wells Ranch-USXAA 35-19 Wellsite
Unused motor oil drums / drip trays
prior insp.



Colorado Oil & Gas Conservation Commission
40.44699, -104.40843, 1438.0m, 129°
02/21/2020 03:47:59 PM

Photo #4

Wells Ranch-USXAA 35-19 Wellsite
*Unused motor oil drums / drip trays: **NOW Removed***