

# Inspection Photos

API: 071-08450

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/21/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08450 | Date: 2/21/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road. Rock rip/rap has been installed near the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08450 | Date: 2/21/2020

## Inspection Photos



**Photo 2.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08450 | Date: 2/21/2020

## Inspection Photos



**Photo 3.** The vegetation is well established along the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08450 | Date: 2/21/2020



## Inspection Photos



**Photo 5.** Well marker of the PA well is installed at location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08450 | Date: 2/21/2020