

Inspection Photos
Operator: Kinder Morgan
Location #: 313577
Date: 2/20/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northwestern fill slope from the northwestern corner facing northeastward. Revegetation is progressing here with grasses such as sand dropseed, Indian ricegrass, crested wheatgrass, and James galleta, as well as shrubs such as rubber rabbitbrush.



Photo 3. View of the northeastern project area from the northeastern corner facing southeastward.



Photo 4. View of the reference area, comprised of pinyon juniper woodland, mixed cliffrose shrubland, and grasses such as Indian ricegrass and sand dropseed in the understory.