

Inspection Photos
Operator: Kinder Morgan
Location #: 313480
Date: 2/20/2020



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the eastern project area from the southeastern edge facing northward. Revegetation is progressing with grasses such as western wheatgrass, James galleta, and sand dropseed.



Photo 3. View of area in the western project area with bare soils that appears to be salt-impacted. Soils will likely need testing and amendment for successful revegetation.



Photo 4. Another view of bare and sparse vegetation on soils within the western project area.



Photo 5. View of the reference area, comprised of pinyon juniper woodland, mixed cliffrose shrubland, and grasses such as Indian ricegrass and sand dropseed in the understory.