

Inspection Photos  
Operator: Kinder Morgan  
Location #: 313505  
Date: 2/20/2020



Photo 1. View of the western project area from the southwestern corner facing northward.





Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass and thickspike wheatgrass, as well as volunteer shrubs such as rubber rabbitbrush.





Photo 3. View of unused cement pad and electrical equipment within the northeastern project area.



Photo 4. 2017 Google Earth aerial imagery overview of location.





Photo 5. View of the reference area, comprised of pinyon juniper woodland, mixed cliffrose shrubland, and grasses such as Indian ricegrass and sand dropseed in the understory.