

Final Reclamation and Stormwater Inspection

February 21, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 333018

Inspection Document #: 697501149

Weld County, CO

SENE Section 7 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STEPHENS-65N66W
/7SENE
Location ID: 333018



Photo 1. Photo taken from the plugged and abandoned well location, facing West. Photo illustrates the well location is now within a new housing development. There was no evidence of oil and gas equipment at the well location.

Inspection Photos
Location Name: STEPHENS-65N66W
/7SENE
Location ID: 333018



Photo 2. Photo taken from the entrance of the offsite tank battery location, facing West. Photo illustrates location has been blocked off to prohibit entry.

Inspection Photos
Location Name: STEPHENS-65N66W
/7SENE
Location ID: 333018



Photo 3. Photo taken from the northwestern offsite tank battery location, facing West. Photo illustrates Operator has removed all equipment and appears to be performing weed management (i.e., mowing).

Inspection Photos
Location Name: STEPHENS-65N66W
/7SENE
Location ID: 333018



Photo 4. Photo taken from the central offsite tank battery location, facing South. See comments under Photo 3.