

# Final Reclamation and Stormwater Inspection

February 21, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 330046

Inspection Document #: 697501155

Weld County, CO

SWNW Section 8 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WIEDEMAN #8-5H6  
Location ID: 330046



**Photo 1.** Photo taken from the well and tank battery location, facing West. Photo illustrates all equipment has been removed and the area has been returned to cropland. COGCC staff will conduct a follow up inspection at a future date to ensure compliance with Rule 1004.

Inspection Photos  
Location Name: WIEDEMAN #8-5H6  
Location ID: 330046



**Photo 2.** Photo taken from the well and tank battery location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: WIEDEMAN #8-5H6  
Location ID: 330046



**Photo 3.** Photo taken from the well and tank battery location, facing East. See comments under Photo 1.