

Final Reclamation and Stormwater Inspection

February 21, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 332871

Inspection Document #: 697501157

Weld County, CO

SENE Section 8 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIEDEMAN-65N66W
/8SENW
Location ID: 332871



Photo 1. Photo taken from the western well and tank battery location, facing East. Photo illustrates all equipment has been removed and the area has been returned to cropland. COGCC staff will conduct a follow up inspection at a future date to ensure compliance with Rule 1004.

Inspection Photos
Location Name: WIEDEMAN-65N66W
/8SENW
Location ID: 332871



Photo 2. Photo taken from the eastern well and tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: WIEDEMAN-65N66W
/8SENW
Location ID: 332871



Photo 3. Photo taken from the well and tank battery location, facing South. See comments under Photo 1.