

# Final Reclamation Inspection

February 21, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 330224

Inspection Document #: 697501161

Weld County, CO

NESW Section 8 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WIEDEMAN #8-11H6  
Location ID: 330224



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates Operator has removed all equipment. COGCC staff will conduct a follow up inspection at a future date to ensure compliance with Rule 1004.

Inspection Photos  
Location Name: WIEDEMAN #8-11H6  
Location ID: 330224



**Photo 2.** Photo taken from the offsite tank battery location, facing South. Photo illustrates Operator has removed all equipment. COGCC staff will conduct a follow up inspection at a future date to ensure compliance with Rule 1004.