

Inspection Photos
Operator: Kinder Morgan
Location #: 428397
Date: 2/20/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is weedy, largely supporting annual weeds such as mustard and cheatgrass.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is sparse with significant areas supporting little desirable vegetation. Scattered perennial grasses observed.



Photo 4. Birdseye view of typical vegetative cover within the interim reclamation area. Observed vegetation is largely annual weeds such as cheatgrass and mustard spp.



Photo 5. View of the reference area, comprised of sagebrush shrubland and grass field vegetation.