

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611




Photo 3 – Unmarked Risers west of Separator



Photo 4 – Unused Equipment inside Tank Berm

