

**Inspection Photos**  
**Location Name: Pronghorn D-9 PAD**  
**Location ID: 436843**



**Photo 1 – Tank Battery**




**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: Pronghorn D-9 PAD**  
**Location ID: 436843**



**Photo 3 – D-X-9 Well missing Wellhead Sign**



**Photo 4 – Unmarked Riser at Wellheads**

**Inspection Photos**  
**Location Name: Pronghorn D-9 PAD**  
**Location ID: 436843**



**Photo 5 – Unmarked Risers East of Compressor**



**Photo 6 – Unmarked Riser East of Compressor**

Inspection Photos  
Location Name: Pronghorn D-9 PAD  
Location ID: 436843



**Photo 7 – Unmarked Risers East of Compressor**



**Photo 8 – Unmarked Riser West of Compressor**