Inspection Photos Location Name: Pronghorn 41-9 Location ID: 306047



Photo 1 – Well recently Plugged and Abandoned. Unused Casing and Wellhead parts still on location



Photo 2 – Wellhead Sign

