

Inspection Photos
Location Name: Faith LC34-785 PAD & Econode
Location ID: 440020



Photo 1 – Faith Econode

Photo 2 – Faith Econode

Inspection Photos
Location Name: Faith LC34-785 PAD & Econode
Location ID: 440020



Photo 3 – Westside Water Tanks – Most Tanks are missing Content, Capacity and NFPA Labels

Photo 4 – Eastside Water Tanks – Most Tanks are missing Content, Capacity and NFPA Labels

Inspection Photos
Location Name: Faith LC34-785 PAD & Econode
Location ID: 440020



Photo 5 – Unused walkover steps and pipes



Photo 6 – Christine LC27-755 & 765 Wellheads

Inspection Photos
Location Name: Faith LC34-785 PAD & Econode
Location ID: 440020



Photo 7 – Ann LC34-755 & 765 Wellheads



Photo 8 – Faith LC34-775 & 785 Wellheads

Inspection Photos
Location Name: Faith LC34-785 PAD & Econode
Location ID: 440020



Photo 9 – Jessica LC27-775 & 785 Wellheads