

A.C. McLaughlin 37
API: 05-103-06333
Inspection: 700400180




Photo 1. Location.



A.C. McLaughlin 37
API: 05-103-06333
Inspection: 700400180



Photo 2. Well head sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

A.C. McLaughlin 37
API: 05-103-06333
Inspection: 700400180



Photo 3. Cable trash next to chemical container.