

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



**Photo #1 – Google Earth aerial photo of subject facility.  
Aerial photo is dated 6/17/2016.**

**Photo #2 – View of lower tank battery, looking southeast.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #3 – Vertical heated separators.



Photo #4 – Horizontal heated separator



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #5 – Horizontal heated separator



Photo #6 – Gas meters



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #7 – 24 bbl methanol tank in lower tank battery, note faded sign.



Photo #8 – Tank labels damaged at lower tank battery (south tank).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #9 – Valve on south tank lacks bullplug.



Photo #10 – Valve on north tank lacks bullplug, condensate staining observed in this location.





## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



**Photo #11 – Hole in lower tank battery liner noted in previous Field Inspection Report (doc #699700034).**



**Photo #12 – Photo (#4) from previous Field Inspection Report (doc #699700034, photo dated 9/19/2019). Similarities in size and shape of hole as well as patterns in nearby paint suggest that this is the same location as previous photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



**Photo #13 – Additional hole in lower tank battery liner**



**Photo #14 – View of fenced wellheads, from west.**





## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



**Photo #15 – View of wellheads outside of fenced area, from east.**



**Photo #16 – View of upper tank battery, from northwest.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #17 – View of upper tank battery loadout area. Note condensate staining on ice.



Photo #18 – Close up view of condensate accumulation on upper tank battery loadout equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #19 – Condensate accumulation in loadout area.



Photo #20 – Unidentified drum in loadout area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



**Photo #21 – Hole in upper tank battery liner appears to have been patched previously.**



**Photo #22 – Day tanks located between upper tank battery and pump house.**

**Note: icy conditions and tight quarters prevented complete inspection of the visible portions of the upper tank battery liner on inspection date.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #23 – Day tanks located north of upper tank battery.



Photo #24 - Additional day tank located west of valve building.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Shideler-68S93W 1SWNE (G1SW) Pad

Location ID: #334069 & Spill/Release ID: #466951

Inspection Date: February 25, 2020



Photo #25 – View of waste containers located west of pump house.



Photo #26 – Close up of liner beneath waste containers.

