



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 11, 2020 1:46:10 PM MST
Server Receive Date:	Feb 11, 2020 1:46:20 PM MST
Reference Number:	20200211-18132721565
Location:	468 Co Rd 305, Durango, CO 81303, USA Feb 11, 2020 1:40:23 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Aug 13, 2019
Well Name	CUGNINI GAS UNIT A 4
API Number	50670943200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soils around hydraulic pump.

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stained soils around the wellhead.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description of corrective action 4
Summary of all work completed

Cleaned up stained soils around the A2 wellhead.

Cleaned up stained soils around the hydraulic pump and both wellheads.