

Inspection Photos
Location Name: Clarks Lake MSSU 15-1
Location ID: 307173



Colorado Oil And Gas Conservation Commission
40.74229, -104.98592, 1607.0m
02/26/2020 11:01:38 AM

Wellhead sign



Colorado Oil And Gas Conservation Commission
40.74232, -104.98586, 1604.0m
02/26/2020 11:02:27 AM

Tubing pressure

Inspection Photos
Location Name: Clarks Lake MSSU 15-1
Location ID: 307173



Casing pressure



Bradenhead pressure