



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 13, 2020 8:45:55 PM MST
Server Receive Date:	Feb 13, 2020 8:46:00 PM MST
Reference Number:	20200214-18132997455
Location:	13 Road 51921, Bloomfield, NM 87413, USA Feb 13, 2020 8:44:07 PM MST [ <a href="#">View Map</a> ]

Information

Name	l.guerrero@kosinm.com
Date	Jun 11, 2019
Well Name	BAIRD GAS UNIT A 2
Location Name (Other)	BAIRD GAS UNIT A 4
API Number	50670970400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up stained soils along the side of the pump jack.

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stained soils along the side of the other pump jack.

Photo of third corrective action completed



Completed work description of corrective action 3

Installed rock armored run downs.

Photo of fourth corrective action completed



Completed work description of corrective action 4

Built berm around pad.

Additional photos



Summary of all work completed

Cleaned up stained soils along the side of both pump jacks. Installed rock armored run downs. Built diversion berms around well pad.