



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Feb 14, 2020 1:21:36 PM MST
Server Receive Date:	Feb 14, 2020 1:21:42 PM MST
Reference Number:	20200214-18133070222
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Feb 14, 2020 1:21:27 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Jun 7, 2019
Well Name	SHORT, ORAN W, A 2
API Number	50670852400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up containment soils from exhaust muffler and installed drip box.

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stained soils around the engine oil day tank.

Photo of third corrective action completed



Completed work description of corrective action 3

Reinstalled carsonite marker on rig anchor.

Photo of fourth corrective action completed




Completed work description of corrective action 4

Additional photos



Additional photos



Summary of all work completed

Cleaned up stained soils around the exhaust muffler and engine day oil tank. Installed exhaust muffler box. Marked all the rig anchors. Picked up all trash and debris.