

Inspection Photos

Location Name: LARAMIE ENERGY LLC Vega Pad /4

Location ID: 334454



Photo #0642 from entrance to location



Photo #0643 unused piping next to separator.

Inspection Photos
Location Name: LARAMIE ENERGY LLC Vega Pad /4
Location ID: 334454



Photo #0644 unused thread half and nipple on separator.



Photo #0645 unused bull plugs on tank burner.