

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /4A

Location ID: 334463



Photo #0652 from entrance to location



Photo #0653 Chemical tank label weathered and not legible.