

Final Reclamation and Stormwater Inspection

February 25, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 333249

Inspection Document #: 697501167

Weld County, CO

NWSE Section 12 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHEEP-65N67W /12NWSE
Location ID: 333249



Photo 1. Photo taken from the entrance of the well location access road, facing West. Photo illustrates the culvert and access road point have not been removed per Rule 1004.

Inspection Photos
Location Name: SHEEP-65N67W /12NWSE
Location ID: 333249



Photo 2. Photo taken from the entrance of the well location access road, facing Northwest. Photo illustrates portions of the access road have been recently disturbed from a pipeline. COGCC staff will have to make a future inspection during the next active growing season to evaluate vegetative compliance.

Inspection Photos
Location Name: SHEEP-65N67W /12NWSE
Location ID: 333249



Photo 3. Photo taken from the southern location, facing Northwest. Photo illustrates that crop do not appear to be reflective of reference area crop levels. COGCC staff will have to make a future inspection during the next active growing season to evaluate vegetative compliance.

Inspection Photos
Location Name: SHEEP-65N67W /12NWSE
Location ID: 333249



Photo 4. Photo taken from the northern location, facing South. See comments under Photo 3.