

**Inspection Photos**  
**Operator: Logos Operating**  
**Location #: 067-05775**  
**Date: 2/27/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the project area from the well pad entrance facing northwestward. Vegetation is established within the interim reclamation areas, largely with smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the southwestern project area facing northward.



Photo 4. View of the reference area, comprised of grass field, in a dormant vegetative condition at this time.