

Inspection Photos

Location Name: COALMONT 14-8 CA DATE 2-28-20

API#: 05-071-07743

INSP. #: 695102223



Colorado Oil & Gas Conservation Commission
37.00407, -104.48593, 61°
2020/02/27 15:24:02



Colorado Oil & Gas Conservation Commission
37.00407, -104.48593, 133°
2020/02/27 15:25:52

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: COALMONT 14-8 CA DATE 2-28-20
API#: 05-071-07743
INSP. #: 695102223



PHOTO 3: GAS METER CAL. REPORT

PHOTO 4: FLUID LEVEL IS ABOVE 2' FREEBOARD MARKER, I SPOKE WITH ED ROMERO WITH EVERGREEN TO HAVE PIT PULLED. Lower fluid level so at least two feet of freeboard exists per Rule 902.b. CA DATE 2-28-20.