

**Inspection Photos**  
**Location Name: Antelope 18I TB**  
**Location ID: 418173**




**Photo 1 – Wellheads**




**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Antelope 18I TB**  
**Location ID: 418173**



**Photo 3 – Unmarked Risers**



**Photo 4 – Unmarked Risers**