

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

Northwest A S20-25-8C Surface

Sincerely,
Meghan Jacobs

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

3.0 Attachments..... 10

 3.1 Northwest A S20-25-8C Surface – Job Chart10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Northwest A S20-25-8C** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 33 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404		Ship To #: 3901214		Quote #:		Sales Order #: 0905952659					
Customer: EXTRACTION OIL & GAS -				Customer Rep: Hans Cary							
Well Name: NORTHWEST A			Well #: S20-25-8C			API/UWI #: 05-014-20791-00					
Field: WATTENBERG		City (SAP): BROOMFIELD		County/Parish: BROOMFIELD		State: COLORADO					
Legal Description: NW NW-9-1S-68W-1297FNL-779FWL											
Contractor: ENSIGN DRLG				Rig/Platform Name/Num: ENSIGN 147							
Job BOM: 7521 7521											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA\HX38199				Srv Supervisor: Thomas Haas							
Job											
Formation Name											
Formation Depth (MD)		Top		Bottom							
Form Type					BHST						
Job depth MD		1633ft			Job Depth TVD		1633				
Water Depth					Wk Ht Above Floor		5				
Perforation Depth (MD)		From		To							
Well Data											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Casing		9.625		36			0	1633	0	1633	
OH		13.5					0	1653	0	1653	
Tools and Accessories											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Guide Shoe	9.625			1633		Top Plug	9.625		HES		
Float Shoe	9.625					Bottom Plug	9.625		HES		
Float Collar	9.625					SSR plug set	9.625		HES		
Insert Float	9.625					Plug Container	9.625		HES		
Stage Tool	9.625					Centralizers	9.625		HES		
Fluid Data											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Red Dye Spacer	Red Dye Spacer			10	bbl	8.33			5	
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal

2	SwiftCem	SWIFTCCEM (TM) SYSTEM	625	sack	13.5	1.74	9.17	8	5731
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Fresh Water	Fresh Water	123	bbl	8.33				
Cement Left In Pipe		Amount	42 ft		Reason Shoe Track			Shoe Joint	
Mix Water:	pH 7	Mix Water Chloride:	<300 ppm			Mix Water Temperature:	66 °F		
Cement Temperature:	N/A	Plug Displaced by:	8.33 lb/gal F.W.			Disp. Temperature:	66 °F		
Plug Bumped?	Yes	Bump Pressure:	520 psi			Floats Held?	Yes		
Cement Returns:	33 bbl	Returns Density:	N/A			Returns Temperature:	N/A		
Comment Plug bumped at calculated displacement, final circulating pressure of 520 psi, floats held, .5 bbl back. 33 bbl of cement to surface.									

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DH Density (ppg)	Comb Pump Rate (bbl/min)	DS Pump Press (psi)	Pump Stg Tot (bbl)	Comments
Event	1	Call Out	Call Out	9/2/2019	08:00:00	USER					CREW CALLED OUT AT 08:00 9/2/2019 REQUESTED ON LOCATION 14:00 9/2/2019. CREW PICKED UP CEMENT, 100 LBS SUGAR, AND PLUG CONTAINER FROM FORT LUPTON, CO. BULK 660: 110995045/10866497 Bulk 660: 11027117/10679720 PUMP ELITE: 11897034/11645460
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	9/2/2019	12:00:00	USER					DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW
Event	3	Crew Leave Yard	Crew Leave Yard	9/2/2019	12:30:00	USER					STARTED JOURNEY MANAGEMENT. CREW STAGED ON LOCATION NEXT TO RIG.
Event	4	Arrive At Loc	Arrive At Loc	9/2/2019	13:00:00	USER					END JOURNEY MANAGEMENT. MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING: 36# 9.625" J-55 @ 1633', 42' SHOE JOINT, 13.5" OPEN HOLE, 8.5 PPG WELL FLUID, FRESH WATER DISPLACEMENT.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	9/2/2019	15:00:00	USER					HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH

											LOCATION, RIG UP AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	9/2/2019	15:10:00	USER					CREW STAGED EQUIPMENT AND RIGGED UP BULK, IRON, AND WATER HOSES TO PERFORM JOB.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	9/2/2019	18:00:00	USER					MEETING WITH HALLIBURTON AND RIG PERSONNEL. COMMUNICATED POTENTIAL SAFETY HAZARDS AND JOB DETAILS.
Event	8	Start Job	Start Job	9/2/2019	21:02:54	COM4	8.33	0.00	1.00	0.00	START JOB DATA RECORDING.
Event	9	Test Lines	Test Lines	9/2/2019	21:05:23	COM4	8.27	0.00	25.00	4.30	PRESSURE TESTED IRON TO 3500 PSI. KICKOUTS SET @ 500 PSI, KICKED OUT @ 1600 PSI, 5TH GEAR STALL OUT @ 1800 PSI.
Event	10	Pump Spacer 1	Pump Spacer 1	9/2/2019	21:12:25	COM4	8.29	0.00	6.00	0.00	PUMP 10 BBL OF FRESH WATER WITH RED DYE.
Event	11	Pump Cement	Pump Cement	9/2/2019	21:16:11	COM4	13.40	3.90	149.00	11.10	PUMP 625 SKS OF SWIFTCM @ 13.5 LB/GAL, 1.74 YIELD, 9.17 GAL/SK, 193.7 BBLs, TOL @ SURFACE, DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	12	Shutdown	Shutdown	9/2/2019	21:47:47	COM4	15.99	0.00	31.00	238.30	SHUTDOWN TO DROP TOP PLUG.
Event	13	Drop Top Plug	Drop Top Plug	9/2/2019	21:48:32	COM4	15.62	0.00	12.00	238.30	PLUG LEFT PLUG CONTAINER, VERIFIED BY COMPANY MAN.
Event	14	Pump Displacement	Pump Displacement	9/2/2019	21:48:34	COM4	15.61	0.00	12.00	238.30	BEGIN PUMPING CALCULATED

											DISPLACEMENT OF 123 BBL FRESH WATER.
Event	15	Cement Returns to Surface	Cement Returns to Surface	9/2/2019	22:02:58	USER	8.44	5.40	537.00	98.90	CEMENT RETURNED TO SURFACE 90 BBL INTO DISPLACEMENT, 33 BBL OF CEMENT TO SURFACE.
Event	16	Bump Plug	Bump Plug	9/2/2019	22:09:25	COM4	8.51	0.00	906.00	124.90	PLUG BUMPED AT CALCULATED DISPLACEMENT, FINAL CIRCULATING PRESSURE OF 520 PSI.
Event	17	Check Floats	Check Floats	9/2/2019	22:10:25	USER	8.48	0.00	184.00	124.90	RELEASED PRESSURE BACK TO THE TRUCK, FLOATS HELD, RECIEVED .5 BBL BACK TO THE TRUCK.
Event	18	End Job	End Job	9/2/2019	22:11:28	COM4	8.47	0.00	4.00	0.00	END JOB DATA RECORDING.
Event	19	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	9/2/2019	22:15:00	USER	8.50	0.00	3.00	0.00	DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	20	Rig-Down Completed	Rig-Down Completed	9/2/2019	22:40:00	USER					ALL HALLIBURTON ITEMS WERE STOWED FOR TRAVEL.
Event	21	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	9/2/2019	22:50:00	USER					DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	22	Crew Leave Location	Crew Leave Location	9/2/2019	23:00:00	USER					THANK YOU FOR USING HALLIBURTON - THOMAS HAAS AND CREW.

3.0 Attachments

3.1 Northwest A S20-25-8C Surface – Job Chart

