

# Inspection Photos

API: 055-06153

Operator: PETROGLYPH OPERATING

Inspection Date: 2/27/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020

## Inspection Photos



**Photo 1.** Facing west along the former access road. Vegetation appears to be well established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020

## Inspection Photos



**Photo 2.** The sign and t-post remain and needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020

## Inspection Photos



**Photo 3.** Facing toward the location. Vegetation is well established at the location. It appears vehicle tracks are traveling thru the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020

## Inspection Photos



**Photo 4.** Facing south toward the location. Vegetation appears to be fully established at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020

## Inspection Photos



**Photo 5.** Facing north toward the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06153 | Date: 2/27/2020