

Inspection Photos

Location Name: WELLS RANCH-USX AA-66N63W /27SENW

Location #: 309701



Photo #1

Wells Ranch-USX AA 27-6 (05-123-25268) Wellsite

Plugged & Abandoned | PA

~ 30 yds.

Reclamation progressing



Photo #2

Wells Ranch- USX AA 27-3 Battery site

Abandoned: All Equipment Removed

Reclamation progressing

Formerly served Wells Ranch USX AA 27-6, 27-19

UPV 27-4G3, 27-5G3

(Plugged & Abandoned | PA)