

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2020

Submitted Date:

02/28/2020

Document Number:

696102385**FIELD INSPECTION FORM**Loc ID 310414 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292734	WELL	SI	09/01/2017	OW	123-26374	WELLS RANCH- USX AA 27-3	TA

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Reclamation progressing.
 Abandoned Battery SE corner GPS coordinates: 40.462720, -104.429860

Abandoned Centralized Battery formerly served 5 Location IDs (310414, 309701, 306640, 330211, 330270).
 (Well(s): 1: Temporarily Abandoned | TA ;4: Plugged & Abandoned | PA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.462720,-104.429860
Comment: Battery Abandoned. Equipment removed. Abandoned Centralized Battery formerly served 5 Location IDs (310414, 309701, 306640, 330211, 330270). (Well(s): 1: Temporarily Abandoned TA ; 4: Plugged & Abandoned PA).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: Battery Abandoned. Equipment removed.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment: Battery Abandoned. Equipment removed.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 292734 Type: WELL API Number: 123-26374 Status: SI Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 07/2016.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.
 Locked-Out, Tagged Out | LOTO.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FR 02/28/2020 at approximately 11:52 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH- USX AA-66N63W /27NENW Location ID: 310414 Well Name: Wells Ranch- USX AA 27-3 API: 05-123-26374 Location County: Weld County, Colorado Weather: Mostly sunny.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.462720, -104.429860</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (310414, 309701, 306640, 330211, 330270). (Well(s): 1: Temporarily Abandoned TA ; 4: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102386	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081388