

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2020

Submitted Date:

02/28/2020

Document Number:

696102387

**FIELD INSPECTION FORM**

Loc ID 309701 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290872	WELL	PA	02/01/2018	OW	123-25268	WELLS RANCH-USX AA 27-6	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Reclamation progressing.  
Abandoned Battery SE corner GPS coordinates: 40.462720, -104.429860  
  
Abandoned Centralized Battery formerly served 5 Location IDs (310414, 309701, 306640, 330211, 330270).  
(Well(s): 1: Temporarily Abandoned | TA ;4: Plugged & Abandoned | PA).

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Plunger Lift

# 0

corrective date

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 290872 Type: WELL API Number: 123-25268 Status: PA Insp. Status: PA

**Workover**

**Comment:** Plugged & Abandoned | PA.  
Well appears to be cut / capped.  
Form 6 doc. #401373483 indicates plugging, cut/cap date: 07/18/2017. Approved.

**Corrective Action:**

**Date:**

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FR 02/28/2020 at approximately 12:05 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: WELLS RANCH-USX AA-66N63W /27SEW                      Location ID: 309701                      Well Name: Wells Ranch-USX AA 27-6                      API: 05-123-25268                      Location County: Weld County, Colorado                      Weather: Mostly sunny.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. ALL equipment has been removed.                      Reclamation progressing.                      Abandoned Battery SE corner GPS coordinates: 40.462720, -104.429860</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (310414, 309701, 306640, 330211, 330270).                      (Well(s): 1: Temporarily Abandoned   TA ; 4: Plugged &amp; Abandoned   PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/28/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102388	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081389">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081389</a>