

Inspection Photos
Location Name: Ross 41-24 2-29-20
Location ID: 321487



Photo 1 facing West

Photo 2 facing South

Inspection Photos
Location Name: Ross 41-24 2-29-20
Location ID: 321487



Photo 3 Well head

Photo 4

Inspection Photos
Location Name: Ross 41-24 2-29-20
Location ID: 321487



Photo 5 mud tracking on road leaving location heading South.

Photo 6 mud tracking on road leaving location heading North

Inspection Photos
Location Name: Ross 41-24 2-29-20
Location ID: 321487



Colorado Oil & Gas Conservation Commission
8828 E County Line Rd, Longmont, CO 80504, USA
40.12913, -105.05557, 4904.3ft, 333°
02/29/2020 11:16:40

Photo 7 NG Sweeper cleaning road