

**Inspection Photos**  
**Location Name: Antelope F-15 PAD**  
**Location ID: 429977**




**Photo 1 – Eastside Tank Battery**




**Photo 2 – Westside Tank Battery**

**Inspection Photos**  
**Location Name: Antelope F-15 PAD**  
**Location ID: 429977**



**Photo 3 – Unmarked Risers East of Gas Lift Meter House**



**Photo 4 – Unmarked Risers East of Gas Lift Meter House**



**Inspection Photos**  
**Location Name: Antelope F-15 PAD**  
**Location ID: 429977**



**Photo 5 – Unmarked Risers East of Gas Lift Meter House**



**Photo 6 – Unmarked Risers and Stained Soil West of Compressor**