

Inspection Photos

Location Name: WELLS RANCH-65N63W /2NWSE

Location #: 305577




Photo #1

Wells Ranch 33-2 (05-123-23181) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

*Reclamation progressing
prior insp.*



Photo #2

Wells Ranch 33-2, 34-2, 43-2, 44-2 Battery site

Abandoned: *Most Equipment removed*

Reclamation progressing

Unused Equipment: 2 - Gas meter runs, risers
prior insp.

Inspection Photos

Location Name: WELLS RANCH-65N63W /2NWSE

Location #: 305577



Photo #3

Wells Ranch 33-2, 34-2, 43-2, 44-2 Battery site

Abandoned: ALL Equipment removed

Reclamation progressing

Unused Equipment: 2 - Gas meter runs, risers

Now removed