

Inspection Photos
Location Name: Klaenhammer 3-A
Location ID: 311769



Photo 1. Access roads not maintained for winter.