

Inspection Photos  
Operator: BP America  
API #: 067-07767 Date:  
2/27/2020



Photo 1. View of the project area from the southwestern edge facing center.





Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of the southern project area from the southwestern edge facing southeastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass, sand dropseed, and rubber rabbitbrush.





Photo 4. View of the reference area, comprised of grass field, in a dormant vegetative condition at this time.