

Inspection Photos
Location Name: UPRR – BESSIE #1
Location ID: 320144



Photo #1 tank



Photo #2 missing Bullplug

Inspection Photos
Location Name: UPRR – BESSIE #1
Location ID: 320144



Photo #3 separator



Photo #4 wellhead

Inspection Photos
Location Name: UPRR – BESSIE #1
Location ID: 320144



Photo #5 leak at wellhead