

Final Reclamation Inspection

February 25, 2020

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 323391

Inspection Document #: 697501177

Weld County, CO

SENW Section 14 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



Photo 1. Photo taken from the tank battery location, facing West. Photo illustrates Operator has removed all equipment. No noxious weeds or stormwater erosion was observed. The well location and its associated offsite tank battery location are now within commercial final land use.

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



Photo 2. Photo taken from the tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



Photo 3. Photo taken from the tank battery location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



02.25.2020 12:24

Photo 4. Photo taken from the tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



Photo 5. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SHANNON #14-1
Location ID: 323391



Photo 6. Photo taken from the well location, facing South. See comments under Photo 1.