

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



Photo #0684 from entrance to location



Photo #0690 Tank label weathered and not legible.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



Photo #0686 Location over grown with debris and weeds.



Photo #0688 Location over grown with debris and weeds.



## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



**Photo #0689 Location over grown with debris and weeds.**