

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Network time is not synchronize
Local: Mar 3, 2020 at 1:49:14 PM MST
+39.3670, -108.292



Network time is not synchronize
Local: Mar 3, 2020 at 1:53:11 PM MST
+39.3671, -108.292

Photo #0693 from entrance to location

Photo #0697 Tank label weathered and not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #0694 Location over grown with debris and weeds.



Photo #0695 Location over grown with debris and weeds.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



Photo #0696 Location over grown with debris and weeds.