

Inspection Photos

Location Name: WELLS RANCH AA-66N63W /26SWNW

Location #: 333283



Photo #1

Wells Ranch AA 26-12HZB (05-123-29499) Wellsite

Temporarily Abandoned | TA

*Invalid Emergency number posted
prior insp.*



Photo #2

Wells Ranch AA 26-12HZB Wellsite

Temporarily Abandoned | TA

Valid Emergency number NOW posted

Inspection Photos

Location Name: WELLS RANCH AA-66N63W /26SWNW

Location #: 333283



Colorado Oil & Gas Conservation Commission
40.45946, -104.41121, 1450.0m, 214°
03/02/2020 04:34:04 PM

Photo #3

Wells Ranch AA 26-05 (05-123-25380) Wellsite

Temporarily Abandoned | TA

prior insp.



Colorado Oil & Gas Conservation Commission
40.46145, -104.40897, 1453.0m, 194°
03/02/2020 04:55:42 PM

Photo #4

Wells Ranch AA 26-05, 26-12H2B, 26-04 Battery site

Abandoned: All Equipment Removed

Reclamation progressing

Formerly served Wells Ranch AA 26-03, 26-06

(Plugged & Abandoned | PA)

prior insp.