

Inspection Photos
Location Name: Sheep 20-12
Location ID: 333249



Photo 1: Wellhead; unused equipment, no sign



Photo 2: Tank Battery; no signage posted



Inspection Photos
Location Name: Sheep 20-12
Location ID: 333249



Photo 3: Unused equipment; disconnected gas meter house

Photo 4: Unused equipment

