

Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 1: Wellhead Sign



Photo 2: TA pumpjack



Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 3: No signage posted



Photo 4: Pumpjack



Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 5: Pumpjack Sign



Photo 6: Pumpjack



Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 7: Pumpjack Sign



Photo 8: Pumpjack

Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 9: Barrel not in containment, trash, unused equipment



Photo 10: Tank Battery Sign



Inspection Photos
Location Name: Winter 29-D Pad
Location ID: 433397



Photo 11: Tank Battery Sign

