

# Final Reclamation Inspection

March 3, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320313

Inspection Document #: 697501181

Adams County, CO

NWSW Section 12 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 1.** Photo taken from the western well and tank battery location, facing East. Photo illustrates Operator appears to have initiated final reclamation activities and may also be prepping for remediation activities.

Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 2.** Photo taken from the northern well and tank battery location, facing East. Photo illustrates equipment remains at location.

Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 3.** Photo taken from the central well and tank battery location, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 4.** Photo taken from the entrance of the location along a portion of the access road, facing South. See comments under Photo 1.