

# Inspection Photos

API: 071-09288

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/3/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09288 | Date: 3/3/2020

## Inspection Photos



**Photo 1.** Facing southeast through Little Bingham Canyon. The road has deep ruts and is not being maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09288 | Date: 3/3/2020

## Inspection Photos



**Photo 2.** Facing south through Little Bingham Canyon. The road has deep ruts and is not being maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09288 | Date: 3/3/2020

## Inspection Photos



**Photo 3.** Facing southwest as it ascends the hillside The road has deep ruts and is not being maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09288 | Date: 3/3/2020

## Inspection Photos



**Photo 4.** Facing southwest along the main road. The road is in need of maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09288 | Date: 3/3/2020

Inspection Photos



Photo 5. Facing northwest toward the location.

