

Inspection Photos

API: 071-08321

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/4/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 3/4/2020

Inspection Photos



Photo 1. Facing west along the main lease road in Alamosito Canyon. The road has vehicle ruts and is not being maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 3/4/2020

Inspection Photos



Photo 2. Facing southwest toward the access road. The road has deep ruts and is not being maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 3/4/2020

Inspection Photos



Photo 3. Facing back toward the access road from the location. The road is inaccessible and needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 3/4/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 3/4/2020