

Inspection Photos

API: 071-09132

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/4/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09132 | Date: 3/4/2020

Inspection Photos



Photo 1. Facing northwest along the main lease road toward the location. The road has deep ruts and is not being maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 3/3/2020

Inspection Photos



Photo 2. Facing northwest along the main lease road toward the location. The road has deep ruts and is not being maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 3/3/2020

Inspection Photos



Photo 3. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09132 | Date: 3/3/2020