

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/04/2020

Submitted Date:

03/04/2020

Document Number:

696102458

FIELD INSPECTION FORM
 Loc ID 302578 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|-----------------|
| , | | dnr_cogccengineering@state.co.us | |
| , | | NBL_DJBU_Inspections@nblenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 299567 | WELL | SI | 11/01/2019 | OW | 123-29419 | WELLS RANCH USX AA 25-09 | TA |

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Reclamation progressing.
 Abandoned Battery SE corner GPS coordinates: 40.453750, -104.381080

Abandoned Centralized Battery formerly served 4 Location IDs (302578, 302580, 310011, 310007).
 (Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Location

| | | | |
|--------------------|----------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|--|
| Emergency Contact Number: | |
| Comment: | <input style="width: 500px;" type="text"/> |
| Corrective Action: | <input style="width: 500px;" type="text"/> |
| Date: | <input style="width: 100px;" type="text"/> |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 299567 Type: WELL API Number: 123-29419 Status: SI Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 02/2017.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI tag for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On WED 03/04/2020 at approximately 12:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX AA-66N63W /25NESE Location ID: 302578 Well Name: Wells Ranch USX AA 25-09 API: 05-123-29419 Location County: Weld County, Colorado Weather: Mostly sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.453750, -104.381080</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (302578, 302580, 310011, 310007). (Well(s): 3: Temporarily Abandoned TA ; 1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 03/04/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696102459 | Site photos | http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085474 |