

Inspection Photos
Location Name: Hill 6T-HZ Pad
Location ID: 431696



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos
Location Name: Hill 6T-HZ Pad
Location ID: 431696



Photo 3: Equipment removed



Photo 4: Stained Soil Removed

