

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 3: Labeling installed



Photo 4: Labeling installed; NO BBLs

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 5: Labeling installed; NO BBLs



Photo 6: Stained soil removed

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 7: Stained soil



Photo 8: Stained soil

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 9: Stained soil



Photo 10: Stained soil removed

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 11: Stained soil removed



Photo 12: Risers LO/TO

Inspection Photos
Location Name: Weld 152 Pad
Location ID: 435175



Photo 13: Heater treater removed, risers LO/TO



Photo 14: Trash removed